



*Above left:* The blast door at the bottom of the western spiral staircase. The corrosion is a consequence of the lower floor having been under water for a prolonged period.

*Above right:* Control gear for the standby generator, with powerhouse ventilation ducting above.

*Left:* The upper floor of the bunker, in use as a carpet warehouse. When this photograph was taken the lower floor was submerged in stagnant seepage water.