




*Above:* Looking down the main western stairs from the upper to the lower floor of the bunker. This photograph was taken in 2001 before the lower floor was pumped dry. The water can be seen just below the top of the blast door. Crates of air filters can be seen on the concrete shelf above the stairs.



*Above right:* Two spiral staircases provided emergency exit routes from the lower floor of the bunker. This view of the upper landing of the south staircase illustrates the thickness of the concrete floor slab between the upper and lower levels.



*Below right:* The bottom of the ornate, cast-iron spiral staircase in the western emergency exit shaft.